TRANSMISSION 722.6## ## as of 2871384 as of 17.4.01,
722.7## ## as of 0153700 as of 9.7.01

To avoid malfunctions from metal particles, a magnet is placed in the oil pan.



P27.40-2027-01

i

The magnet can be retrofitted in the field.